

In the Drawings

The attached new formal drawings include the following changes:

Figure 3, addition of the label "(PRIOR ART)";

Figure 4, addition of the label "(PRIOR ART)",

deletion of all line arrows,

change "SYSTCK" to "SYSCLK",

change reference number "31" to "45",




change reference number "32" to "46",

change reference number "33" to "47";

Figure 5, addition of the label "(PRIOR ART)";

Figure 6, addition of the label "(PRIOR ART)";

Figure 8, addition of signal direction arrows into block 201 for signal lines "TDI" and "MODE", from block 201 to block 210, from block 210 to block 202, from block 204 to block 202, from block 212 to block 213, from block 213 to block 202, out of block 202 for signal line "TDO" and into block 202 on signal line "Mode".

FIG. 2
(PRIOR ART)





FIG. 4
(PRIOR ART)



*FIG. 5
(PRIOR ART)*



*FIG. 6
(PRIOR ART)*




FIG. 7




FIG. 8